



# NÁRAZNÍKOVÉ PRUŽINY - KRUHOVÉ


Typ DS




Typ KD




Typ KE




Typ KG




Typ .16




Typ KK




Typ KH



Typ KP-D



Typ KP-E



D <sub>1</sub>	D <sub>2</sub>	H <sub>1</sub>	Závit 1 (Gxh)	ShA	Tvar	Typ
15	-	14	M 4x13	55	-	DS
25	-	18,5	M 6x18	55	-	DS
40	-	28	M 8x10	55	-	DS
50	-	28	M 10x33	55	-	DS
70	-	43	M 10x28	55	-	DS
75	-	37	M 12x37	55	-	DS
18	-	18	M 6x10	50	77.16	.16
25	-	25	M 6x12	50	78.16	.16
35	-	35	M 8x16	50	76.16	.16
50	-	50	M 10x20	50	79.16	.16
70	-	70	M 12x24	50	80.16	.16
12	-	12	M 4x10	55	-	KD
14	-	6,3	M 4x 4	55	-	KD
25	-	12	M 6x18	55	-	KD
25	-	14	M 4x10	55	-	KD
25	-	17	M 6x18	55	-	KD
45	-	21	M 8x46	55	-	KD
50	-	18	M 10x28	55	-	KD
50	-	50	M 10x28	55	-	KD
125	-	45	M 16x45	55	-	KD
50	-	35	M 10x10	55	-	KE
25	-	15	M 6x18	55	-	KG
38	30	35	M 10x27	55	-	KH
43	30	35	M 10x27	55	-	KH
43	30	50	M 10x25	55	-	KH
24	-	17	M 8x20	55	-	KK
25	-	16	M 8x20	55	-	KK
40	-	24	M 8x28	55	-	KK
50	-	28	M 8x28	55	-	KK
50	-	45	M 10x35	55	-	KK
10	-	10	M 5x12	55	-	KP-D

D <sub>1</sub>	D <sub>2</sub>	H <sub>1</sub>	Závit 1 (Gxh)	ShA	Tvar	Typ
20	-	15	M 6x10	55	-	KP-D
20	-	24	M 6x18	55	-	KP-D
25	-	16	M 6x18	55	-	KP-D
25	-	20	M 6x18	55	-	KP-D
30	-	30	M 8x20	55	-	KP-D
30	-	36	M 8x20	55	-	KP-D
35	-	40	M 8x23	55	-	KP-D
50	-	50	M 10x28	55	-	KP-D
50	-	61	M 8x28	55	-	KP-D
50	-	67	M 8x33	55	-	KP-D
50	-	68	M 10x38	55	-	KP-D
70	-	58	M 12x32	55	-	KP-D
75	-	89	M 12x37	55	-	KP-D
95	-	80	M 16x42	55	-	KP-D
118	-	77	M 16x41	55	-	KP-D
10	-	10	M 5	55	-	KP-E
20	-	15	M 6	55	-	KP-E
20	-	24	M 6	55	-	KP-E
25	-	16	M 6	55	-	KP-E
25	-	20	M 6	55	-	KP-E
30	-	30	M 8	55	-	KP-E
30	-	36	M 8	55	-	KP-E
35	-	40	M 8	55	-	KP-E
50	-	50	M 10	55	-	KP-E
50	-	61	M 8	55	-	KP-E
50	-	67	M 8	55	-	KP-E
50	-	68	M 10	55	-	KP-E
70	-	58	M 12	55	-	KP-E
75	-	89	M 12	55	-	KP-E
95	-	80	M 16	55	-	KP-E
118	-	77	M 16	55	-	KP-E